

# BMW Z8 Club e.V.



BMW Z8 Club e.V. ♦ Kaiserhammer 45 ♦ D-95168 Marktleuthen

## Circular letter to all Club Members!

**President**  
Olaf Hetze  
Wittenberger Str. 44  
D-80993 München  
Germany  
☎ +49 (0) 160-8217799  
**e-mail**  
Praesident@Z8-Club.de

Your sign, your message from

Our sign  
Jürgen Wunderlich

Date  
September 11, 2006

**Treasurer**  
Jutta Haenisch  
Priscoß-Str. 18  
D-63755 Alzenau  
Germany  
☎ +49 (0) 171-4218218  
**e-mail**  
Finanzen@Z8-Club.de

## Availability Retrofit Performance Package for BMW Z8

Dear club members,

with great expectations, we eagerly waited for the performance package, which has now, after significant efforts become available at the BMW dealerships in Germany.

**The BMW Part No. is 51 71 0 420 758  
and the price without installation is EUR 371.20 incl. VAT.**


**Chairman for Technic**  
Jürgen Wunderlich  
Kaiserhammer 45  
D-95168 Marktleuthen  
Germany  
☎ +49 (0) 9235-967400  
**e-mail**  
Technik@Z8-Club.de

**Chairman for Sports  
and Tourism**  
Norbert Galasso  
Püntenstr. 13  
CH-8143 Stallikon  
Switzerland  
☎ +41 (0) 44-7778370  
**e-mail**  
Touristik@Z8-Club.de

The retrofit can be performed by any BMW dealer or representation, and according to the installation manual is calculated with approx. 8.5 hours work time. Prior to the installation, the car's software will be updated to the latest version, and an alignment will be performed. The Performance Package consists of two strut tower supports (incl. attaching parts) and a strut brace, which will be attached to the frame structure in front of the strut tower.

**Chairman for Public  
Relations**  
Helge Brauch  
Varoneser Str. 1  
D-81547 München  
Germany  
☎ +49 (0) 89-64270430  
**e-mail**  
Oeffentlichkeit@Z8-Club.de

**Mailing Address**  
BMW Z8 Club e.V.  
Club Office  
Jürgen Wunderlich  
Kaiserhammer 45  
D-95168 Marktleuthen  
Germany  
☎ +49 (0) 9235-967450  
☎ +49 (0) 9235-967460  
**e-mail**  
Sekretariat@Z8-club.de



**Internet**  
www.Z8-Club.de

**Bank Account**  
Sparkasse  
Aschaffenburg-Alzenau  
Account-Nr.: 8463929  
Bank Code: 795 500 00  
IBAN:  
DE 60 7955 0000 0008  
4639 29  
SWIFT-BIC:  
BYLADEM 1ASA

**Headquarter**  
München, VR 19058

The Performance Package can not be used on ALPINA V8 Roadsters, because the strut brace would make contact with the engine. Whether or not there will be a special retrofit for Alpina cars is unknown to me at this point.

For installation, the front wheels, the inner covers of the wheel houses, the headlamps, and the air intake housings will be dismantled. The strut brace will be

attached on both sides in 3 places using blind rivet nuts (12 mm bores needed in frame structures) and torx screws (M8). The strut supports will be supported by an additional reinforcement ring from above.


### Illustration strut support



### Attaching points strut brace



**Installation position in the car** (strut brace is not attached, but only positioned in the picture!)



Many thanks and best regards.

Representing the Board



Jürgen Wunderlich  
Acting President

**Attachment:** Installation manual retrofit Performance Package BMW Z8  
(currently available in German only)